

APPENDIX C - SITE PHOTOGRAPHS



Photo 1.1: Drainage line and existing crossings (access roads) to site B.



Photo 1.2: Instream and bank habitat at Site B drainage line.



Photo 1.3: Instream and bank habitat at Site B drainage line.



Photo 1.4: Lower lying crossing (not recommended to be used as a drainage line crossing)



Photo 1.5: Higher lying crossing (recommended to be upgraded and used as a drainage crossing for access to site B)



Photo 2.1 Upper reaches of transformed drainage line at site A.



Photo 2.2 Lower reaches of transformed drainage line at site A.



Photo 2.3 Instream habitat condition of upstream reaches of transformed/excavated drainage line at site A.



Photo 2.4 Instream habitat conditions of downstream reaches of transformed drainage line and wetland area below dam wall at site A.



Photo 3.1: Site C



Photo 4.1: Channeled drainage line along southeastern border of site D.



Photo 4.2: Instream habitat condition of channeled drainage line along southeastern border of site D.