

APPENDIX D – SITE PHOTOS



Photograph 1: View of a portion of the study area with minimal vegetation



Photograph 2: View of a portion of the study area with minimal vegetation



Photograph 3: View of a portion of the study area with minimal vegetation



Photograph 4: View of potential drainage channel



Photograph 5: View of potential drainage channel



Photograph 6: View of a portion of the study area with little to no vegetation



Photograph 7: View of a portion of the study area



Photograph 8: View of a portion of the study area



Photograph 9: View towards the south in the PV study area with a quartzite bedrock seam exposed on the surface.



Photograph 10: View towards the west from the south-eastern corner of the PV study area. The Sishen-Saldanha Railway is faintly visible at far left (arrowed).



Photograph 11: View towards the south across the eastern part of the PV study area showing bare sandy substrate with denser vegetation in the background along an ephemeral water course.



Photograph 12: View towards the south in the south-western part of the PV study area showing a sandy plain with minimal vegetation.



Photograph 13: View towards the south of the extensive gravel plain in the western part of the PV study area. A bedrock outcrop is visible at far right.



Photograph 14: A small pan in the south-western part of the PV study area.

POWERLINE ROUTE PHOTOS:

The power line route commences on sandy substrate in the east (Figure A) and then crosses a wide water course which has many trees in it (Figure B). It crosses the farm dam and then proceeds over a gravel plain with occasional sandy areas (Figures C and D).



Figure B: View towards the south of the area in the watercourse just east of the farm dam.



Figure C: View towards the east in the central part of the power line route showing dense gravel and the water course leading to the farm dam in the background.



Figure D: View towards the west near the western end of the power line route showing dense gravel.