APPENDIX C: SITE PHOTOS

BEFORE



Photo1: BEFORE: Vehicle Bridge. Picture taken from east in a westerly direction.



Photo2: BEFORE: River. Picture taken from west in a north-easterly direction.



Photo3: BEFORE: River. Silted and covered with kikuyu grass.

Idas Valley erf 9445 s24G

<u>AFTER</u>



Photo 4: AFTER: Starting point of completed Gabion at Vehicle Bridge. Picture taken from east in a westerly direction

Idas Valley erf 9445 s24G



Photo 5: After: Completed Gabion. Picture taken from west in a north-easterly direction.



Photo 6: After: Completed Gabion. Picture taken from South in a north-easterly direction.



Photo 7: After: End of completed Gabion. Area with excavation (half-completed gabion construction). Picture taken from south in a north-easterly direction.




Photo 8: After: Proposed site where Gabion is still to be completed (clean, inspect and construct Gabion). Pooling of water due to excavation that has taken place. Picture taken from north-east in a south-westerly direction.

AERIAL PHOTOS:



Image1: DATED 5 January 2018 (AFTER)



Image2: DATED 22 May 2017 (BEFORE)



Vantage Points of photos 1 - 8

Scale: 1:2 257 Date created: June 8, 2018

